



Updates in IMMS 3.4.0.0

New Features:

Added full GPRS Functionality.

Added 2 new GPRS comm module types (ACC-P2P-GPRS, ACC-P2P-GPRS)

Allow either a URL or IP address for TCP/IP site connections.

Other Changes:

Fixed: LAN IP port does not default to 10001 on older databases

Fixed: Alarm log download was aborted when a SSG reset by central alarm was encountered

Fixed: The port sensor settings for ADM-attached sensors is now handled correctly whenever the database is loaded.

Recent Changes (version 3.2.0.0):

Added TCPIP Functionality (for ACC-COM-LAN in Ethernet systems).

Added ability to have multiple hardwired Sites via multiple CCCs, by selecting individual com ports at Site level.